Overhead Lines Galvanic Corrosion Challenges

PRESENTED BY – Ravinder Singh

www.preformed.co.nz



1

Purpose of an Electrical Connector

- Connect two electrical conducing medium
 - > Conduct electricity
 - ➤ Satisfy mechanical requirements
- ❖ For the Life of the connection





Keys to a Good Connection

- Choose the right Material for application
 - > Copper vs Aluminium vs Other
- Maximize Contact Area
 - ➤ Increase "A Spots" (electrical contact points)
- Optimize Pressure (Force)



Maintain all three for the life of the connection



2

Material Selection

- Choose the right Material for application
 - ➤ Copper vs Aluminium vs Other



Copper to Copper

Aluminium to Copper

Aluminium to Aluminium

Copper Connector

Aluminium Connector

Aluminium Connector*



Δ

Electrical Contact


❖ Maximize Contact Area

➤ Increase "A Spots" (electrical contact points)



"A" spots are contact points between two conducting surfaces that actually conduct and transfer current from one surface to other

The actual electronic contact surface may be as little as 10% of the visible contact surface






5

Optimize Pressure

Optimize Pressure (Force)




Pressure helps create and maintain "A" spots (electrical contact points)
Too much pressure, however, can cause material deformation and lead to reduction in conductive area





Reduction of pressure over life will reduce contact spots and lead to failure


Thermal expansion and relaxation can cause reduce pressure











NZ Harsh Environment Case Study





11

NZ Harsh Environment Case Study



Aluminium to Copper Connection
Oct 2017 – Feb 2020 2.5 Years





Aluminium to Copper Connection Via Bimetallic pin July 2018 – May 2020 ~2 Years



